

# Inspection Photos

ID: 444661

Operator: STRACHAN EXPLORATION INC

Inspection Date: 9/24/2024

County: Prowers



## Inspection Photos



**Photo 1.** Facing east toward the compressor facility.



## Inspection Photos



**Photo 2.** Facing northeast toward the tank. The leak that had occurred was not cleaned up. There is insufficient labeling and signage at the tank. Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 444661 | Date: 9/24/2024

## Inspection Photos



**Photo 3.** Facing east toward the tank. The leak that had occurred was not cleaned up. There is insufficient labeling and signage at the tank . Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 444661 | Date: 9/24/2024

## Inspection Photos



**Photo 4.** There is stained soils still observed inside the secondary from the previous spill. There are green flags put around the impacted area.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 444661 | Date: 9/24/2024