

Inspection Photos

API: 099-06872

Operator: STRACHAN EXPLORATION INC

Inspection Date: 9/24/2024

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road. The ruts along the road have been repaired but no stabilization was performed to prevent erosion reoccurrence.



Inspection Photos



Photo 2. Facing southwest at the wellsite. Sign is posted at the wellhead.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 099-06872 | Date: 9/23/2024

Inspection Photos



Photo 3. Facing southwest by the well. There is unused equipment and drilling pipe that needs to be removed. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 099-06872 | Date: 9/23/2024

Inspection Photos



Photo 4. Facing toward the fiberglass tank. The fence has been repaired.

