

Interim Reclamation and Stormwater Inspection

Date: 09/10/2024

Operator: DENOVA SEQUESTRATION LLC - 10790

Location ID: 483817

Inspection Document #: 708201606

Washington County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Denova 1
Location ID: 483817



Photos 1 & 2. Erosion degradation evident with inadequate stormwater control measures observed along the access road. Additional maintenance and/or more robust control measures required.

Inspection Photos
Location Name: Denova 1
Location ID: 483817



Photos 3 & 4. Taken along the access road; see comments in Photo 1 & 2.

Inspection Photos
Location Name: Denova 1
Location ID: 483817



Photos 5 & 6. Taken along the access road; see comments in Photo 1 & 2.

Inspection Photos
Location Name: Denova 1
Location ID: 483817



Photos 7 & 8. Taken along the access road; see comments in Photo 1 & 2.

Inspection Photos
Location Name: Denova 1
Location ID: 483817



Photos 9 & 10. Taken along the access road; see comments in Photo 1 & 2.

Inspection Photos
Location Name: Denova 1
Location ID: 483817



Photos 11 & 12. Taken along the access road; see comments in Photo 1 & 2.

Inspection Photos
Location Name: Denova 1
Location ID: 483817



Photos 13 & 14. Taken along the access road; see comments in Photo 1 & 2.

Inspection Photos
Location Name: Denova 1
Location ID: 483817



Photos 15 & 16. Taken along the access road; see comments in Photo 1 & 2.

Inspection Photos
Location Name: Denova 1
Location ID: 483817



Photos 17 & 18. Taken along the access road; see comments in Photo 1 & 2.

Inspection Photos
Location Name: Denova 1
Location ID: 483817



Photo 19. Emergency contact number has been updated with larger font and the unused equipment has been moved off location. Operator will need to submit documentation of permission to store equipment on adjacent landowner.

Inspection Photos
Location Name: Denova 1
Location ID: 483817



Photo 20. Erosion degradation observed near the entrance to the drilling pad.



Photo 21. Erosion degradation near the southwest corner of the drilling pad, near the sediment detention area.



Photo 22. Erosion degradation observed on the southern portion of the drilling pad.



Photo 23. Erosion degradation observed on the southern portion of the drilling pad.



Photo 24. Erosion degradation observed on the southern portion of the drilling pad.



Photo 25. Degraded straw wattles around the topsoil stockpile need to be removed as it's considered debris.

Inspection Photos
Location Name: Denova 1
Location ID: 483817



Photo 26. South side of topsoil stockpile; see comments in Photo 25.



Photo 27. Facing southwest from on top of the topsoil stockpile. It does not appear that interim reclamation activities have been performed.

Inspection Photos
Location Name: Denova 1
Location ID: 483817



Photo 28. Stained soil around the wellhead appears to have been removed.

Inspection Photos
Location Name: Denova 1
Location ID: 483817



Photo 29. Stained soil around the wellhead appears to have been removed.

Inspection Photos
Location Name: Denova 1
Location ID: 483817



Photo 30. Northern parking areas do not appear to have been reclaimed.



Photo 31. Southern parking areas do not appear to have been reclaimed.