

Inspection Photos
Location: Hoffman Earl 1
Location ID: 321229
API # 05-011-06126



Photo 1 – Well placard on meter house, placard not legible



Photo 2 – Wellhead and equipment



Inspection Photos
Location: Hoffman Earl 1
Location ID: 321229
API # 05-011-06126



Photo 3 – Heater Treater



Photo 4 – Tank Battery, secondary containment not adequate

Inspection Photos
Location: Hoffman Earl 1
Location ID: 321229
API # 05-011-06126



Photo 5 – Secondary Containment not adequate



Photo 6 – Tank Placard does not reflect current Operator