

**Inspection Photos**  
**Location: Bourne 1**  
**Location ID: 321213**  
**API # 05-011-06032**



**Photo 1 –Well placard, incorrect Operator information**

**Photo 2 – Wellhead and equipment**

**Inspection Photos**  
**Location: Bourne 1**  
**Location ID: 321213**  
**API # 05-011-06032**



**Photo 3 – Heater Treater**

**Photo 4 – Meter House**

**Inspection Photos**  
**Location: Bourne 1**  
**Location ID: 321213**  
**API # 05-011-06032**



**Photo 5 – Pipe risers not capped and no OOSLAT**

**Photo 6 – Tank Battery, Secondary Containment not adequate**

**Inspection Photos**  
**Location: Bourne 1**  
**Location ID: 321213**  
**API # 05-011-06032**



**Photo 7 – Secondary Containment with impacted soils stored in 5 gallon buckets**

**Photo 8 – Undesirable weeds on location**

**Inspection Photos**  
**Location: Bourne 1**  
**Location ID: 321213**  
**API # 05-011-06032**



**Photo 9 – Undesirable weeds on location**

**Photo 10 – Undesirable weeds on location**