

Inspection Photos

Location: Wollert D 1

Location ID: 321230

API # 05-011-06138



Photo 1 –Wellhead, well placard at wellhead

Photo 2 – Location looking east to wellhead from tank battery

Inspection Photos
Location: Wollert D 1
Location ID: 321230
API # 05-011-06138



Photo 3 – Meter house and equipment

Photo 4 – Meter house settling

Inspection Photos
Location: Wollert D 1
Location ID: 321230
API # 05-011-06138



**Photo 5 – Partially Buried Separator and equipment,
Gate in disrepair**

Photo 6 – Tank Battery

Inspection Photos
Location: Wollert D 1
Location ID: 321230
API # 05-011-06138



Photo 7 – Tank Battery fencing in disrepair

Photo 8 – Secondary Containment inadequate

Inspection Photos
Location: Wollert D 1
Location ID: 321230
API # 05-011-06138



Sep 24, 2024 at 2:54:33 PM
+38.248145,-102.786138
ECMC



Sep 24, 2024 at 2:54:35 PM
+38.248145,-102.786138
ECMC

Photo 9 – Spill Kit

Photo 10 – AST