

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2024

Submitted Date:

09/26/2024

Document Number:

710500375

FIELD INSPECTION FORM

Loc ID 321229 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
6 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 83130
 Name of Operator: STRACHAN EXPLORATION INC
 Address: 992 S 4TH AVE SUITE 100-461
 City: BRIGHTON State: CO Zip: 80601

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Stacy L Bear		stacy@strachanexploration.com	Field inspections
HARMS, JASON		jharms@strachanexploration.com	
Costa, Ryan		ryan.costa@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206379	WELL	PR	08/01/2018	GW	011-06126	HOFFMAN, EARL 1	EG

General Comment:
 This is an Environmental Inspection for the Hoffman Earl 1, Well API 05-011-06126, located in Bent County, Colorado. There is an Open Remediation Project # 36168 associated with the Tank Battery

Location

Lease Road:

	Type Access		
comment:	Two track road through pasture		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:

	Type OTHER		
Comment:	Well placard located on meter house. Well Placard is illegible.		
Corrective Action:	Install sign to comply with Rule 605.d. Reclamation Inspection # #713600502, #713600769 and # 713601181 address placard. Original Corrective action date shall apply	Date:	09/25/2024

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLS	STEEL AST		
Comment:	Tank remains on location; Form 27 Doc # 403848701 filed for the decommissioning of the tank battery, Operator comment states Decommissioning activities will commence Q3 2024. Operator shall provide notification to area EPS once activities commence. Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance				
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	The secondary containment is insufficient to contain a spill. Previous corrective action was not completed.			
Corrective Action:	Original Correctiove action date shall apply.			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 206379 Type: WELL API Number: 011-06126 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500376	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6723201