

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2024

Submitted Date:

09/26/2024

Document Number:

710500377

FIELD INSPECTION FORMLoc ID 321213 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 83130

Name of Operator: STRACHAN EXPLORATION INC

Address: 992 S 4TH AVE SUITE 100-461

City: BRIGHTON State: CO Zip: 80601

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Harms, Jason		Jason@strachanexploration.com	Strachan Exploration
L, Stacy		stacy@strachanexploration.com	Field inspections
Costa, Ryan		ryan.costa@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206286	WELL	PR	11/01/2017	GW	011-06032	BOURNE 1	EI

General Comment:

This is an Environmental Inspection for the Bourne 1, API 05-011-06032, located in Bent County, Colorado. There is an open remediation for the decommissioning of the Tank Battery, Remediation Project # 36166

Location**Lease Road:**

Type			
comment:	Two Track road through Irrigated Farm Ground		
Corrective ActionL		Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Well Placard at tank battery does not reflect the current Operator.		
Corrective Action:	Install sign to comply with Rule 605.e Original Corrective action date shall apply	Date:	09/25/2024

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type	OTHER		
Comment:	There are five, 5-gallon buckets in the secondary containment. FIRR Document # 403853644 Operator comments states; dug up stained earth into 6ea 5 gal buckets and stored in secondary containment		
Corrective Action:	Dispose of contaminates soils in accordance with Rule 905. Operator shall provide waste manifest once contaminated soils are removed	Date:	10/30/2024
Type	WEEDS		
Comment:	There are undesirable weeds on the location and location border		
Corrective Action:	Comply with Rule 606. Original CA date shall apply	Date:	09/25/2024
Type	OTHER		
Comment:	There are unmarked pipe risers on the location near the secondary containment area. Pipe risers shall be marked and OOSLAT shall be applied		
Corrective Action:	Comply with 606. Original Corrective action date shall apply	Date:	09/25/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLS	STEEL AST		,

Comment:	Tank remains on location. Form 27 Doc # 403843896 filed for the decommissioning of the tank battery, Operator comment states Decommissioning activities will commence Q3 2024. Operator shall provide notification to area EPS once activities commence. Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance	
Corrective Action:		Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	The secondary containment is insufficient to contain a spill. Previous corrective action was not completed.			
Corrective Action:	Original corrective action Date shall apply			Date: 09/25/2024

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

