

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2024

Submitted Date:

09/26/2024

Document Number:

710500385

FIELD INSPECTION FORM

Loc ID 321241 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 992 S 4TH AVE SUITE 100-461
City: BRIGHTON State: CO Zip: 80601

Findings:

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
L, Stacy		stacy@strachanexploration.com	Field inspections
Harms, Jason		Jason@strachanexploration.com	Strachan Exploration
Costa, Ryan		ryan.costa@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256995	WELL	TA	06/01/2020	GW	011-06173	SEMMENS 1A	EI

General Comment:

This is an Environmental Inspection for the Seemens 1 A, API 05-011-06173, located in Bent County, Colorado. There is an open Remediation Project # 25046 for the decommissioning of the well location.

Location

Lease Road:			
Type			
comment:	Two track road through pasture		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:			
Comment:	No placard on site		
Corrective Action:		Date:	

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	There are pipes located on the south side of the location		
Corrective Action:	Remove unused equipment per Rule 606	Date:	10/28/2024
Type	UNUSED EQUIPMENT		
Comment:	There is unused fencing materials on the location		
Corrective Action:	Remove unused equipment per Rule 606	Date:	10/28/2024

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Flow Line	#		
Comment:	There are two Pipe Risers located on the location associated with Flowline Facility ID # 470774.		
Corrective Action:		Date:	
Type: Other	#		
Comment:	There is no wellhead on site		
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	Tanks have been removed				
Corrective Action:				Date:	

Paint	
Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 256995 Type: WELL API Number: 011-06173 Status: TA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Operator shall commence quarterly reporting under Remediation Project # 25046.	sanchezcc	09/26/2024
Once Remediation activities are completed, the Operator shall preform final reclamation in accordance with Rule 1004.	sanchezcc	09/26/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500386	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6723206