

Interim Reclamation and Stormwater Inspection

Date: 9/19/24

Operator: Fritzler Resources Inc - 31257

Location ID: 475344

Inspection Document #: 713901008

Washington County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: West Fork Unit

63S55W/19SWNW

Location ID: 475344



Photo 1. The photo was taken at the tank battery location facing Northeast. The photo illustrates the Operator location sign has been painted covering the emergency contact number and other pertinent operator information.

Photo 2. The photo was taken at the tank battery location facing Northeast. The photo illustrates the tank placards on the location need replaced.

Inspection Photos

Location Name: West Fork Unit

63S55W/19SWNW

Location ID: 475344



Photo 3. The photo was taken at the tank battery location facing Northwest. The photo illustrates the interim areas have some perennial grass growth with some tumbleweeds, russian thistle and kochia, predominantly along the edges.



Photo 4. The photo was taken at the tank battery location facing East. Refer to the comment for photo 3.

Inspection Photos

Location Name: West Fork Unit

63S55W/19SWNW

Location ID: 475344



Photo 5. The photo was taken at the tank battery location facing North. The photo illustrates the West pit wall is eroding.



Photo 6. The photo was taken at the tank battery location facing North. The photo illustrates the East pit wall is eroding.

Inspection Photos

Location Name: West Fork Unit

63S55W/19SWNW

Location ID: 475344



Photo 7. The photo was taken at the tank battery location facing Southeast. The photo illustrates additional disturbance associated with Remediation Project #9126.

Photo 8. The photo was taken Southeast of the tank battery location facing East. Refer to the comment for photo 7.

Inspection Photos

Location Name: West Fork Unit

63S55W/19SWNW

Location ID: 475344



Photo 9. The photo was taken at the tank battery location facing West. The photo illustrates stained soil within secondary containment at the tanks.

