

Inspection Photos

September 25th, 2024

Operator: American Helium Operating - 10841

Location ID: 381617

Inspection Document #: 714001271

Dolores County, CO

Township: NESW 19 39N 19W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Pribble A1
Location ID: 381617

9/25/24
+37.626442,-108.994615
238° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the eastern portion of the disturbance facing center. Note: Large area that has not been reclaimed per 1004 rules. Area shows little to no vegetation establishment and remnant gravel.

API #: 033-40004

Inspection Photos
Location Name: Pribble A1
Location ID: 381617

9/25/24
+37.626442,-108.994615
307° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Area in towards center of project area that has not been reclaimed properly. Minimal vegetation establishment observed with remnant gravel.

API #: 033-40004

Inspection Photos
Location Name: Pribble A1
Location ID: 381617

9/25/24
+37.626442,-108.994615
263° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Adjacent reference area comprised predominantly of Rabbitbrush and Broom snakeweed.

API #: 033-40004