

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2024

Submitted Date:

09/20/2024

Document Number:

708904632

**FIELD INSPECTION FORM**Loc ID 335478 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Katz, Aaron		aaron.katz@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296693	WELL	PR	05/20/2009	GW	045-16101	SAVAGE RWF 411-26	PR
297597	WELL	PR	05/20/2009	GW	045-16886	SAVAGE RMV 149-26	PR

**General Comment:****CECMC Inspection Report Summary**On 09/19/2024 at approximately 12:00 hours, I, Compliance Specialist, Wayne Smelser  
Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC SAVAGE RWF22-26 Pad.

Location # 335478 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas &amp; in close proximity to NSO Habitat area &amp; Bald Eagle Roost Site.

Location is approximately 450 yards from Porcupine Creek.

Location is approximately 475 yards from Beaver Creek.

While there, I observed workover rig performing casing repair on the SAVAGE RWF 411-26 well.

During this inspection the following compliance issues were observed:

1. Inspected Facilities - Failure to comply with COA on SAVAGE RWF 411-26 well with a CA date of 9/18/2024

2. Inspected Facilities - Failure to comply with COA on SAVAGE RMV 149-26 with a CA date of 9/19/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

This inspection is limited in scope focusing primarily on the SAVAGE RWF 411-26 &amp; SAVAGE RMV 149-26 wells.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Rig sign at intersection of county road & start of lease road		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911/970-285-9377	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Other	# 1		corrective date
Comment:	Accumulator		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Workover rig		
Corrective Action:		Date:	
Type: Other	# 6		
Comment:	Fire extinguishers		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Rig tank		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Rig pump		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 296693 Type: WELL API Number: 045-16101 Status: PR Insp. Status: PR

**Workover**Comment: Please refer to FORM 4 SUNDRY document # 403782337

Operator has failed to comply with condition of approval, well was to be repaired or plugged no later than 9/18/2024.

Corrective Action: Contact CECMC Engineering Group &amp; discuss observed compliance issue.

Date: 09/27/2024

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 297597 Type: WELL API Number: 045-16886 Status: PR Insp. Status: PR

**Cement**Cement Contractor

Contractor Name: \_\_\_\_\_

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Cement Type: \_\_\_\_\_

Comment: Please refer to FORM 4 SUNDRY document # 403782358

Operator has failed to comply with condition of approval, well was to be repaired or plugged no later than 9/19/2024. At time of inspection well had not been repaired or plugged.

Spoke with TEP consultant &amp; was informed that the rig would be moving to this well to perform plugging operations early next week.

Corrective Action: Contact CECMC Engineering Group &amp; discuss observed compliance issue.

Date: 09/27/2024

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited inspection due to ongoing workover rig operations on location.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Inspected Facilities for corrective actions.	smelserw	09/20/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403929887	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6715946">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6715946</a>
708904633	Inspection 708904632 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6715942">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6715942</a>