

Inspection Photos
Operator: Dover Atwood/Envex Baca
Location Name: Thompson 1-24 API: 009-05200



1. SE corner looking NW



2. Erosion on south side of location around water tank

Inspection Photos
Operator: Dover Atwood/Envex Baca
Location Name: Thompson 1-24 API: 009-05200



3. Lease sign mounted to meter run door isn't legible



4. Wellhead with water leg disconnected