

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN 14-26H Pad

Location ID: 323868



Photo # 1998 From entrance to location



Photo # 1999 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN 14-26H Pad

Location ID: 323868



Photo # 2000 Location



Photo # 2001 Location



**Inspection Photos**  
**Location Name: TEP ROCKY MOUNTAIN LLC JUHAN 14-26H Pad**  
**Location ID: 323868**



**Photo # 2002 Location**



**Photo # 2003 Location**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN 14-26H Pad

Location ID: 323868



Photo # 2004 Location



Photo # 2005 Spill response station



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN 14-26H Pad

Location ID: 323868



**Photo # 2006 PRV & rupture disc on separator unit do not comply with CECMC pressure safety device rules or CECMC general safety rules**



**Photo # 2007 PRV & rupture disc on separator unit do not comply with CECMC pressure safety device rules or CECMC general safety rules**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN 14-26H Pad

Location ID: 323868



Photo # 2008 Location