

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 33-36 Pad
Location ID: 335050



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. Location is within Rule 411a Surface Water Intermediate & External Buffers. Location is approximately 236 yards from Beaver Creek.

Section/Township/Range: 36 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Hoepli RWF 33-36 Pad
Location ID: 335050



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Hoepli RWF 33-36 Pad
Location ID: 335050



Photo # 2136 Failure to maintain chemical BMP/chemical tank containment approximately 3/4th full of fluid/BMP insufficient to contain possible spill



Photo # 2137 Failure to maintain chemical BMP/chemical tank containment approximately 3/4th full of fluid/BMP insufficient to contain possible spill

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Hoepli RWF 33-36 Pad
Location ID: 335050



Photo # 2138 Failure to maintain chemical BMP/chemical tank containment approximately 3/4th full of fluid/BMP insufficient to contain possible spill



Photo # 2139 Failure to maintain chemical BMP/chemical tank containment approximately 3/4th full of fluid/BMP insufficient to contain possible spill