

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2024

Submitted Date:

09/23/2024

Document Number:

708302778

**FIELD INSPECTION FORM**Loc ID 334808 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                              | Comment |
|--------------|-------|------------------------------------|---------|
| , TEP        |       | COGCCInspectionReports@terraep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 210763      | WELL | PR     | 10/14/1986  | GW         | 045-06521 | FORSHEE W-22-3  | PR          |
| 210943      | WELL | PR     | 07/15/1997  | GW         | 045-06701 | FORSHEE GV 49-3 | PR          |

**General Comment:****CECMC Inspection Report Summary**

On 9/19/2024 at approximately 12:30, Compliance Inspector Matthew Morris conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC, FORSHEE-67S95W/3NWNE at Location ID #334808 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

1) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               | OTHER  |       |  |
| Comment:           | Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank. |       |  |
| Corrective Action: |  | Date: |  |
| Type               | TANK LABELS/PLACARDS   |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |
| Type               | BATTERY  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |
| Type               | WELLHEAD   |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

Emergency Contact Number:

Comment: 911/(970)285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |                       |       |  |
|--------------------|-----------------------|-------|--|
| Type               | SEPARATOR             |       |  |
| Comment:           | Hog panels            |       |  |
| Corrective Action: |                       | Date: |  |
| Type               | WELLHEAD              |       |  |
| Comment:           | Hog panels/pipe rails |       |  |
| Corrective Action: |                       | Date: |  |
| Type               | TANK BATTERY          |       |  |
| Comment:           | Hog panels            |       |  |
| Corrective Action: |                       | Date: |  |

**Equipment:**

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
| Type: Horizontal Heated Separator | # 1 |       | corrective date |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |

|                       |     |  |       |
|-----------------------|-----|--|-------|
| Type: Bird Protectors | # 1 |  |       |
| Comment:              |     |  |       |
| Corrective Action:    |     |  | Date: |
| Type: Bradenhead      | # 2 |  |       |
| Comment:              |     |  |       |
| Corrective Action:    |     |  | Date: |
| Type: Gas Meter Run   | # 2 |  |       |
| Comment:              |     |  |       |
| Corrective Action:    |     |  | Date: |
| Type: Plunger Lift    | # 1 |  |       |
| Comment:              |     |  |       |
| Corrective Action:    |     |  | Date: |

**Tanks and Berms:**

|                    |   |           |           |         |        |       |
|--------------------|---|-----------|-----------|---------|--------|-------|
| Contents           | # | Capacity  | Type      | Tank ID | SE GPS |       |
| PRODUCED WATER     | 1 | <100 BBLS | STEEL AST |         | ,      |       |
| Comment:           |   |           |           |         |        |       |
| Corrective Action: |   |           |           |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          |                     | Date:               |             |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    |       |
|                    |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: |       |
|                    | Date: |

| Inspected Facilities   |        |       |      |             |           |         |    |               |    |
|--|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:   | 210763 | Type: | WELL | API Number: | 045-06521 | Status: | PR | Insp. Status: | PR |
| Producing Well   |        |       |      |             |           |         |    |               |    |
| Comment:   |        |       |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      |             |           | Date:   |    |               |    |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |             |           |         |    |               |    |
| Facility ID:   | 210943 | Type: | WELL | API Number: | 045-06701 | Status: | PR | Insp. Status: | PR |
| Producing Well   |        |       |      |             |           |         |    |               |    |
| Comment:   |        |       |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      |             |           | Date:   |    |               |    |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |             |           |         |    |               |    |
|  |        |       |      |             |           |         |    |               |    |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment               |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|-----------------------|
| Berms            |                 |                         |                       |               |                          |                       |
|                  |                 | Ditches                 |                       |               |                          |                       |
| Gravel           |                 |                         |                       |               |                          |                       |
| Compaction       | Fail            |                         |                       |               |                          | Lack of stabilization |
|                  |                 | Compaction              |                       |               |                          |                       |
|                  |                 | Gravel                  |                       |               |                          |                       |

Comment: Location surface lacks stabilization with insufficient vehicle tracking BMPs in place to minimize transportation of sediment.

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 10/08/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403931523    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6717865">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6717865</a> |
| 708302779    | Photo Log            | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6717861">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6717861</a> |