

# Inspection Photos

09/26/2024

**Operator:** ANSCHUTZ EXPLORATION CORP -  
3104

**Location ID:** 430927

**Inspection Doc:** 69620635

Rio Blanco County, CO

Aaron Trujillo  
Western Reclamation Work Lead  
ECMC



**COLORADO**


**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



**Photo 1:** Photo taken from the interim areas on the southeast end of the Location. Photos examples showing compaction alleviation pursuant to 1003 requirements has not been performed on the southeast interim areas, and reclaimed access road on the north end of the Location.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



**Photo 2:** Topsoil stockpile. Operator appears to have performed mowing operations. Timing to prevent further spread of weeds is inadequate, as weeds have already seeded out for the year.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



**Photo 3:** Photos examples showing anchor on the southeast end of the pad remains buried, and has not been marked pursuant to Rule 1003.a.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



**Photo 4:** Photos show holes within containment BMP/Liner on the west end of the Location. BMP no longer impervious to contain a spill or release from the impacted materials.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



**Photo 5:** Photo shows leaks at equipment (pipe, northeast end of the Location) have persisted, and spills onto the pad surface have recurred.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



**Photo 6:** Photo shows leaks at equipment (pipe, northeast end of the Location) have persisted, and spills onto the pad surface have recurred.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



**Photo 7:** Continued from photo 6. Operator on site began work on spill at time of inspection. Impacts appear to have impacted all new clean material brought onto the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 430927



**Photo 8:** Photo taken from the behind the compressor equipment. Containment BMP has been reinstalled, and impacted soils appear to have been cleaned/removed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources