

Inspection Photos
Location Name: Cleveland #2
Location ID: 332884



Energy & Carbon Management Commission
40.11106, -104.90296, 1508.7m, 41°
Sep 30, 2024 13:23:08

Photo 1: Location from entrance, overgrown vegetation



Energy & Carbon Management Commission
40.11105, -104.90288, 1511.2m, 19°
Sep 30, 2024 13:22:59

Photo 2: Wellhead Sign

Inspection Photos
Location Name: Cleveland #2
Location ID: 332884



Photo 3: Wellhead, overgrown vegetation



Photo 4: Overgrown vegetation

Inspection Photos
Location Name: Cleveland #2
Location ID: 332884



Photo 5: Unused/disconnected equipment, overgrown vegetation