

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/30/2024

Submitted Date:

09/30/2024

Document Number:

714201729**FIELD INSPECTION FORM**Loc ID 336113 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	<a href="#">all inspections.</a>
Tibbs, Dan	970-539-0664	Dtibbs@kpk.com	
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241390	WELL	PR	05/01/2018	OW	123-09179	CLEVELAND 7	TA

**General Comment:**[This is an audit of CLEVELAND #7 scout card and related documents followed by a field inspection.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	overgrown vegetation on various areas of location. See attached photo		
Corrective Action:	Comply with Rule 606.	Date:	10/30/2024
Type	OTHER		
Comment:	stained soil near pumpjack. See attached photo.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).d.		Date: 10/30/2024

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			

Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241390

Type: WELL

API Number: 123-09179

Status: PR

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; equipment appears to be disconnected

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/03/2024

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Optical Gas Imaging Survey**Survey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.111000 Long: -104.897900Wind: Gusts Speed: 17 (mph) Direction From: NE Weather: Clear Temperature: 75 (F)Assisting Staff Brittani Santistevan Camera #: \_\_\_\_\_☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
1330	PM	1332	PM	Wellhead(s)

Comment: The wellhead does not appear to be ommitting emissions into the atmosphere. See attached photos.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
<p><b>ECMC Inspection Report Summary</b> WEATHER CONDITIONS: sunny, dry ground. On Monday, September 30, 2024 at approximately 1315, I, Inspector Brittani Santistevan, conducted an on-site inspection at CLEVELAND #7 (KP Kauffman Company, Inc.), at API #: 05-123-09179 in WELD COUNTY, Colorado. While there, I observed a TA wellhead. During this inspection the following possible compliance issues were observed: 1. It appears to be overgrown vegetation on various areas of location. Remove to comply with Rule 606. (Corrective Action Date: October 30, 2024) See attached photo #1, 3-5. 2. It appears to be some stained soil near the pumpjack. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f. (2).d. (Corrective Action Date: October 30, 2024) See attached photos #6.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	09/30/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201730	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6728244">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6728244</a>
714201734	Wellhead Video	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6728245">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6728245</a>