

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2024

Submitted Date:

09/24/2024

Document Number:

715500760

**FIELD INSPECTION FORM**Loc ID 315539 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Caerus	(970) 285-2600	COGCC.inspections@caerus oilandgas.com	
Energy, QB	(970) 285-2600	ecmc.inspections@qb- energy.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231007	WELL	SI	10/01/2023	GW	103-08676	CORRAL CREEK 4505	SI

**General Comment:****ECMC Inspection Report Summary**

On Tuesday, 09/24/2024, Inspector Kirby Burchett, attempted to conduct a routine field inspection at Caerus Piceance LLC - QB Energy on the Corral Creek 4505 well, Location #315120, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District and Black Bear area with High Priority, NSO, Density and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Unable to access location due to locked private gate on access road. Operator was unable to provide correct combination for the lock.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Locked private gate denying access to location.			
Corrective Action	Provide key, combinations, or alternate method of access to comply with rule 204.		Date:	09/27/2024
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:	<input type="text"/>			Date: _____
Corrective Action:	<input type="text"/>			
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:			Date:	
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities									
Facility ID:	231007	Type:	WELL	API Number:	103-08676	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____									
Comment: <div>Shut In - October 2023 July 2024 Production Report</div>									
Corrective Action: _____ Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403933279	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6719757">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6719757</a>