

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/01/2024

Submitted Date:

10/01/2024

Document Number:

693807748

FIELD INSPECTION FORM

Loc ID 322519 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10770
Name of Operator: VISION ENERGY LLC
Address: P O BOX 370
City: IGNACIO State: CO Zip: 81137

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
O'Hare, Mollie	970-563-4000	mollieo@maralexinc.com	
Bechtolt, Phoebe	970-563-4000	pbechtolt@maralexinc.com	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Labowskie, Steve		steve.labowskie@state.co.us	
Graves, Jim	970-712-0099	mrinc20@maralexinc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210689	WELL	TA	01/01/2021	CBM	045-06447	MESAGAR 21-1	TA

General Comment:

ECMC staff performed a routine field inspection on 10/1/2024.
Issues were found requiring corrective action.
Any Corrective Actions from previous inspections that have not been addressed are still applicable

Location

Lease Road:			
Type	Access		
comment:	Location is not accessible due to washed out road		
Corrective Action:	Repair and maintain lease road to comply with rule 204.	Date:	11/01/2024

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 80%;" type="text"/>
Corrective Action:	<input style="width: 80%;" type="text"/>
Date:	_____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 210689 Type: WELL API Number: 045-06447 Status: TA Insp. Status: TA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12