

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad

Location ID: 323788



Photo # 2084 From entrance to location



Photo # 2085 Location

# Inspection Photos

Location Name: MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad

Location ID: 323788



Photo # 2086 Location

Photo # 2087 Location

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad

Location ID: 323788



**Photo # 2088 Weeds near meter house that are causing a fire hazard**



**Photo # 2089 Weeds near meter house that are causing a fire hazard**

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad

Location ID: 323788



**Photo # 2090 Weeds within close proximity to wellhead that also constitute a fire hazard**

