

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2024

Submitted Date:

10/01/2024

Document Number:

708904707

FIELD INSPECTION FORM

Loc ID: 323788 Inspector Name: Smelser, Wayne On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 13 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 10550
 Name of Operator: MUSTANG RESOURCES LLC
 Address: P O BOX 13550
 City: BAKERSFIELD State: CA Zip: 93389

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Mustang		nwelch@vaqueroenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210809	WELL	SI	04/01/2024	GW	045-06567	MOORE 27-42-6S-94W	SI

General Comment:

[CECMC Inspection Report Summary](#)
 On 09/26/2024 at approximately 11:14 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad. Location # 323788 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Nest/Roost sites & in close proximity to NSO Habitat area. Location is approximately 104 yards from the Colorado River & 321 yards from Porcupine Creek. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Housekeeping - Weeds near wellhead & meter house that are causing a fire hazard with a CA date of 10/08/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
 This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	No tank battery		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/888-291-8588		
Corrective Action:		Date:	_____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds near wellhead & meter house that are causing a fire hazard		
Corrective Action:	Comply with CECMC weeds/undesirable plant species rules & safety rules	Date:	10/08/2024

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Deadman # & Marked	# 1		
Comment:	Marked		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well is not on plunger lift		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 210809 Type: WELL API Number: 045-06567 Status: SI Insp. Status: SI

Producing Well

Comment: [Producing, well not on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Other						Small amount of rill erosion on location
Gravel						Sparse to none
		Gravel				Sparse in some areas
Compaction						

Comment:

Corrective Action:

Date:

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Housekeeping for corrective action	smelserw	10/01/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904709	Inspection 708904707 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6729754
708904710	Inspection 708904707 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6729755