

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2024

Submitted Date:

10/01/2024

Document Number:

698602409

FIELD INSPECTION FORMLoc ID 304267 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
254285	WELL	PR	01/29/1999	GW	125-08163	MONK 3-4	PR

General Comment:

Routine Inspection.

Location

Lease Road:			
Type	Access		
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access to well location.		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign at wellhead location.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Well sign posted at remote Gas Meter Run.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Content/Quantity/Hazard sign at tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency contact information posted on well sign.

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Stock panel fencing around surface equipment at remote gas metering location.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:	Flowline riser at wellhead with valve and plug.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Tubing in the wellbore. Tubing valve open. Casing valve not connected.		
Corrective Action:		Date:	

Type: Gas Meter Run	# 1	
Comment:	Remote Gas Meter Run located on CR 53 & CR R. Gas Meter Run. Chart in Meter Box dated 9-25-24. Meter Calibration/Test Log dated 3-15-24. Well Inlet Valve open. Gas Outlet Valve open.	
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Shared Remote Gas Meter Shed.	
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Separator Shed at remote Gas Meter Run.	
Corrective Action:		Date:
Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:	At Shared remote gathering location.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	110 BBL
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	None.			
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	254285	Type:	WELL	API Number:	125-08163	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Tubing valve open. Casing valve not connected. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open. Electronic Well File reflects last Production/Status reported 7/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.								
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698602458	Inspection photos.	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6729899