

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/13/2024

Submitted Date:

09/25/2024

Document Number:

717900030

**FIELD INSPECTION FORM**

Loc ID 450411 Inspector Name: Robinson, Taylor On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 8840  
Name of Operator: BLUE CHIP OIL INC  
Address: 155 E BOARDWALK DR STE 400  
City: FORT COLLINS State: CO Zip: 80525

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email               | Comment         |
|--------------|-------|---------------------|-----------------|
| ,            |       | bluechipoil@msn.com |                 |
| ,            |       | bluechipoil@msn.com | All Inspections |

**General Comment:**

This is an environmental inspection for Location ID 450411 Wagner 2-1 (shared location with PDC). Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

| Contents                                | # | Capacity | Type | Tank ID | SE GPS                     |
|---|---|----------|------|---------|----------------------------|
|   |   |          |      |         |                            |
| Comment: <input type="text"/>           |   |          |      |         |                            |
| Corrective Action: <input type="text"/> |   |          |      |         | Date: <input type="text"/> |

Paint

|                  |                      |
|------------------|----------------------|
| Condition        | <input type="text"/> |
| Other (Content)  | <input type="text"/> |
| Other (Capacity) | <input type="text"/> |
| Other (Type)     | <input type="text"/> |

Berms

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance                                   |
|---|----------|---------------------|---------------------|---|
|   |          |                     |                     |   |
| Comment: <input type="text" value="Berm around AST is beginning to recede. Could use some recompacting before it becomes an issue and is not able to properly contain a potential release."/> |          |                     |                     |   |
| Corrective Action: <input type="text" value="Repair or install berms or other secondary containment devices per Rule 603.o."/>  |          |                     |                     | Date: <input type="text" value="10/25/2024"/> |

**Venting:**

|                    |                            |
|--------------------|----------------------------|
| Yes/No             | <input type="text"/>       |
| Comment:           | <input type="text"/>       |
| Corrective Action: | Date: <input type="text"/> |

**Flaring:**

|                    |                            |
|--------------------|----------------------------|
| Type               | <input type="text"/>       |
| Comment:           | <input type="text"/>       |
| Corrective Action: | Date: <input type="text"/> |

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403934776    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6721380">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6721380</a> |
| 717900031    | photo log            | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6721371">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6721371</a> |