

Inspection Photos

API: 099-06285

Operator: LAMAR OIL & GAS EXPLORATION

Inspection Date: 9/24/2024

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south toward the wellsite location. There is a cattle water tank on the south side of the location.



Inspection Photos



Photo 2. Center of the location facing east. This area is where the tank battery existed. It appears there is historic impacts from the tank battery that is impacting vegetation growth.



Inspection Photos



Photo 3. Facing northeast toward the impacted area which is close to the drainage in the upper right..



Inspection Photos



Photo 4. Facing southwest. The location excluding the area around the water tank has not been reclaimed and has mostly bare soils.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. Facing toward the west side of the location. This area was excavated for the wellsite and was never reclaimed.

