

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2024

Submitted Date:

10/02/2024

Document Number:

699700399

**FIELD INSPECTION FORM**

Loc ID 423560 Inspector Name: Heil, John On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10384  
 Name of Operator: GENESIS GAS & OIL COLORADO LLC  
 Address: 1141 NORTH LOOP 1604 E 105-414  
 City: SAN ANTONIO State: TX Zip: 78232

**Findings:**

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Cholas, Nick		nick.cholas@state.co.us	
Roberts, James		j75rober@blm.gov	<a href="#">BLM meeker</a>
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423563	WELL	PR	11/01/2022	CBM	103-11880	CALAMITY RIDGE 14-31	EI

**General Comment:**

[ECMC Environmental Inspection. All previous unresolved CAs for this location still apply to this inspection.](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type OTHER

Comment: Unused equipment and trash and debris observed on location. See photos for details.

Corrective Action: Comply with Rule 606.

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER		OTHER	STEEL AST		
Comment: Tank contents are unknown, tank label displays TEP Rocky Mountain LLC signage.					
Corrective Action: Install sign to comply with Rule 605.h.					Date: _____

**Paint**

Condition

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth		Walls Insufficient	Base Insufficient	Inadequate
Comment: Various sizes of holes and tears in the liner of the tank battery secondary containment structure.				
Corrective Action: Install liner material to ensure spill or released materials will be maintained with containment structure.				Date: _____

**Venting:**

Yes/No

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 423563 Type: WELL API Number: 103-11880 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700402	20240924 Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6731046">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6731046</a>