

# Interim Reclamation and Stormwater Inspection

Date: 10/01/24

Operator: Highpoint Operating Corporation - 10071

Location ID: 436165

Inspection Document #: 713901038

Weld County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

# Inspection Photos

Location Name: RSU Anschutz Fed 4-62-2\_1

SWNW

Location ID: 436165



**Photo 1.** The photo was taken at the well location entrance facing South. The photo illustrates the Operator location sign and access road.



**Photo 2.** The photo was taken along the access road to the well location facing Southeast. The photo illustrates sediment has filled the ditch behind the riprap check dam and should be cleaned out.



# Inspection Photos

Location Name: RSU Anschutz Fed 4-62-2\_1

SWNW

Location ID: 436165



**Photo 3.** The photo was taken at the well location facing North. The photo illustrates the riprap check dam at the cattle guard has been sedimented in.



**Photo 4.** The photo was taken at the well location facing Northwest. The photo illustrates stained soil near diesel tanks.



# Inspection Photos

Location Name: RSU Anschutz Fed 4-62-2\_1

SWNW

Location ID: 436165



**Photo 5.** The photo was taken at the well location facing Northeast. The photo illustrates unused equipment being stored on the production pad.



**Photo 6.** The photo was taken at the well location facing Southeast. The photo illustrates some russian thistle encroachment into the interim area that is dominated in most places by mostly perennial grasses.



# Inspection Photos

Location Name: RSU Anschutz Fed 4-62-2\_1

SWNW

Location ID: 436165



**Photo 5.** The photo was taken at the well location facing Northwest. The photo illustrates the slope has been stabilized with a combination of terracing and perennial grass vegetation.



**Photo 6.** The photo was taken at the well location facing North. The photo illustrates some apparent runoff along the access road between the production facility and the wells to the South.



Inspection Photos

Location Name: RSU Anschutz Fed 4-62-2\_1

SWNW

Location ID: 436165



**Photo 7.** The photo was taken at the well location facing North. The photo illustrates good establishment of perennial grasses in the interim areas with some areas of russian thistle encroachment (one area noted by red arrow).



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 713901038