

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2024

Submitted Date:

09/26/2024

Document Number:

710500387**FIELD INSPECTION FORM**Loc ID 321230 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 83130Name of Operator: STRACHAN EXPLORATION INCAddress: 992 S 4TH AVE SUITE 100-461City: BRIGHTON State: CO Zip: 80601**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Harms, Jason		Jason@strachanexploration.com	<a href="#">Strachan Exploration</a>
L, Stacy		stacy@strachanexploration.com	<a href="#">Field inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206391	WELL	PR	02/01/2024	GW	011-06138	WOLLERT D 1	EI

**General Comment:**

This is an Environmental Inspection for the Wollert D 1, API 05-011-06138, located in Bent County, Colorado. There is an open Remediation Project # 24824 for the decommissioning of the well location and tank battery

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access road to tank battery is adjacent to an irrigation canal		
Corrective ActionL		Date:	
Type	Access		
comment:	Wellhead is located in an irrigated field, at the time of inspection there was no access road to the wellhead		
Corrective ActionL		Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment: Placards were observed at the meter house, tank battery and wellhead

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Fencing at tank battery is inadequate		
Corrective Action:	Repair fencing per Rule 1002	Date:	10/30/2024
Type	SEPARATOR		
Comment:	Fencing at the separator is inadequate, gate in disrepair		
Corrective Action:	Repair fencing per Rule 1002	Date:	10/30/2024

<b>Equipment:</b>			corrective date
Type: Other	#		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1		STEEL AST		,
Comment:	Tank Battery located next to cannal road				
Corrective Action:		Date:			

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	



**Inspected Facilities**

Facility ID: 206391    Type: WELL    API Number: 011-06138    Status: PR    Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
Form 27 Initial Document #403144977 was submitted on 8/29/2022. Operator states the following in the Initial Action Summary; Strachan Exploration proposes to conduct closure operations of the Wollert D#1 wellhead. Plugging operations will begin after the harvest in Q3/4 2022. There are no facilities on this location Cut and Cap operations will be performed a minimum of 5 days after the PTA process completes as per COGCC rules. We will perform appropriate site investigation and field screening pursuant to findings, according to COGCC series 900 rules. PID surveys will be performed based on visual inspection. Should soil samples be needed based on visual inspection, they will be collected and analyzed per rule 915, following the sampling guidelines in 915.e.(2). All waste generated during the process will be managed and disposed of properly as directed in rules 905 and 906.	sanchezcc	09/26/2024
Operator shall implement Quarterly reporting for this remediation project and provide a standalone implementation schedule identifying when decommissioning activities will commence.	sanchezcc	09/26/2024
Operator shall submit a Supplemental Form 27 for Remediation Project #24824 by 10/7/2024		
Wellhead is located in an irrigated field	sanchezcc	09/26/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403936742	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6723218">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6723218</a>
710500388	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6723208">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6723208</a>