

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/02/2024

Submitted Date:

10/03/2024

Document Number:

713400354

FIELD INSPECTION FORM

Loc ID 334507 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 20 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, LARAMIE		cogccnotifications@laramie-energy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277500	WELL	PR	10/29/2007	GW	077-08876	HELLS GULCH FEDERAL 2-9	PR
277501	WELL	PR	02/01/2015	GW	077-08875	HELLS GULCH FEDERAL 2-10	PR
277502	WELL	PR	09/19/2017	GW	077-08874	HELLS GULCH FEDERAL 2-15	PR
277503	WELL	PR	11/18/2008	GW	077-08873	HELLS GULCH FEDERAL 2-16	PR
281422	WELL	PR	09/01/2018	GW	077-08962	HELLS GULCH FEDERAL 2-7	PR

General Comment:

[CECMC Inspection Report Summary](#)

On 10/2/2024 at approximately 12:51, Compliance Inspector Dusty Popejoy conducted an on-site inspection at LARAMIE ENERGY LLC Hells Gulch Federal/2-10 Pad at Location ID #334507 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. Stormwater - Failure to maintain chemical BMP with a CA date of 10/6/2024
2. Housekeeping - Loose barbed wire fencing/wildlife hazard with a CA date of 10/10/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location			
Lease Road:			
Type	Access		
comment:	Access		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Sign at entrance to location is weathered and cracked		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical labeling on tanks on separators		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911/1-800-891-6191		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Loose barbed wire fencing/wildlife hazard near SE side of entrance to location, refer to photos		
Corrective Action:	Comply with CECMC wildlife rules		Date: 10/10/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	All Bradenhead valves are accessible 2-10 well bradenhead is connected to flowline		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		Centralized containment				Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	3	400 BBLs	STEEL AST		,		
Comment:		Telemetry on tank				Date:	
Corrective Action:						Date:	
Paint							
Condition	Inadequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:		Centralized containment				Date:	
Corrective Action:						Date:	
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:							
Flaring:							
Type							
Comment:							
Corrective Action:							

Inspected Facilities

Facility ID: 277500 Type: WELL API Number: 077-08876 Status: PR Insp. Status: PR

Producing Well

Comment:	Producing well	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 277501 Type: WELL API Number: 077-08875 Status: PR Insp. Status: PR

Producing Well

Comment:	Producing well	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 277502 Type: WELL API Number: 077-08874 Status: PR Insp. Status: PR

Producing Well

Comment:	Producing well	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 277503 Type: WELL API Number: 077-08873 Status: PR Insp. Status: PR

Producing Well

Comment:	Producing well	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 281422 Type: WELL API Number: 077-08962 Status: PR Insp. Status: PR

Producing Well

Comment:	Producing well	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams						
		Rip Rap				
		Check Dams				
		Sediment Traps				
Rip Rap						
Sediment Traps						
		Culverts				
Gravel						
		Gravel				
Ditches						
Compaction						
		Compaction				
				Material Handling And Spill Prevention	Fail	Failure to maintain chemical BMP
		Ditches				
Berms						
Seeding						
		Berms				

Comment: 1. Failure to maintain chemical BMP/chemical containment approximately 3/4th full of fluid/not sufficient to contain possible spill

Corrective Action: Comply with CECMC Stormwater rules

Date: 10/06/2024

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400355	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6732640