

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/MV 8-4

Location ID: 334718

Date: 10/3/2024



Northwest Corner of Location – Photo #03883



Wellheads – Photo #03880

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/MV 8-4

Location ID: 334718

Date: 10/3/2024



Separators – Photo #03894



Tank Battery – Photo #03887

Inspection Photos

Location Name: TEP Rocky Mountain LLC, Federal/MV 8-4

Location ID: 334718

Date: 10/3/2024



Weathered and Illegible Battery Sign – Photo #03888



Weathered and Illegible Wellhead Sign – Photo #03885

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/MV 8-4

Location ID: 334718

Date: 10/3/2024



Weathered and Illegible Wellhead Sign – Photo #03886



Open-Ended Load Line – Photo #03889

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/MV 8-4

Location ID: 334718

Date: 10/3/2024



Open-Ended Load Line – Photo #03890



Insufficient Erosion Control; Rill Erosion on Lease Road –
Photo #03896

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/MV 8-4

Location ID: 334718

Date: 10/3/2024



**Insufficient Erosion Control; Rill Erosion on Lease Road –
Photo #03900**



**Insufficient Erosion Control; Transport of Sediment Off of
Lease Road – Photo #03898**