

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 10/3/2024



Location Entrance – Photo #03902



Wellheads – Photo #03910

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 10/3/2024



Oct 3, 2024 at 11:00:32
De Beque CO 81630
United States

Separators – Photo #03903



Oct 3, 2024 at 11:00:56
De Beque CO 81630
United States

Tank Battery – Photo #03904

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 10/3/2024



Weathered and Illegible Wellhead Sign – Photo #03911





Weathered and Illegible Wellhead Sign – Photo #03912

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 10/3/2024



Weathered and Illegible Wellhead Sign – Photo #03913

Weathered and Illegible Wellhead Sign – Photo #03914

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 10/3/2024



Open-Ended Line on Separator – Photo #03906



Open-Ended Line on Separator – Photo #03907

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 10/3/2024



Rill Erosion on Lease Road Into Location – Photo #03918



Transport of Sediment Offsite – Photo #03915

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 10/3/2024



Check Dam BMP Full and Needs Maintenance – Photo #03916



Check Dam BMP Full and Needs Maintenance – Photo #03917