

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/25/2024

Submitted Date:

09/27/2024

Document Number:

707801118

**FIELD INSPECTION FORM**

Loc ID 312674 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
7 Number of Comments  
3 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 ECMC Operator Number: 96790  
 Name of Operator: WILLSOURCE ENTERPRISE LLC  
 Address: 730 17TH ST STE 712  
 City: DENVER State: CO Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccenforcement@state.co.us	Enforcement
Williams, Reed	(303) 575-9696	reed@willsourceenterprise.com	President

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263767	WELL	TA	07/25/2018	GW	077-08760	LITTLE BEAVER 1-20	TA

**General Comment:**

ECMC Inspection Report Summary  
 On Wednesday 9/25/2024, I, Inspector Scott Ramsey, conducted a routine inspection at Willsource Enterprise LLC Little beaver 1-20, at Location # 312674 in Garfield county Colorado.  
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.  
 While there, I observed well is T/A. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

NOAV document # 402842940 in process from 10/14/2021

During this inspection the following compliance issues were observed:  
 1. No well head signage  
 2. Random debris  
 3. MIT is overdue (last MIT done 10/23/2014)  
 Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	No well head siagnage		
Corrective Action:	Provide proper signage	Date:	10/04/2024
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	303-575-9696/911	Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	10/04/2024

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type				corrective date
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:		Date:		
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:		Date:		
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:		Date:		
Type: Bradenhead	# 1			
Comment:				
Corrective Action:		Date:		
Type: Pig Station	# 1			

Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:				
				Date:

**Flaring:**

Type				
Comment:				
Corrective Action:				
				Date:

**Inspected Facilities**

Facility ID: 263767 Type: WELL API Number: 077-08760 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: MIT is overdue (last MIT done 10/23/2014) NOAV document # 402842940 in process from 10/14/2021

Corrective Action: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. A mechanical integrity test will be performed on each Shut-in Well within 2 years of the initial shut-in-T/A date. Subsequently, a mechanical integrity test will be performed on each Shut-in-T/A well on 5-year intervals from the date the initial mechanical integrity test was performed, as long as the Well remains shut-in-T/A. A compliance plan needs to be established with COGCC engineering.

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403937705	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6724613">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6724613</a>
707801122	Photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6724596">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6724596</a>