

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 10/3/2024



Location Entrance – Photo #03940



Wellheads – Photo #03946

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 10/3/2024



Separators – Photo #03942




Tank Battery – Photo #03945

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 10/3/2024



Open-Ended Line – Photo #03943

Open-Ended Line – Photo #03944

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 10/3/2024



Rill Erosion Transporting Sediment from Location – Photo #03939



Rill Erosion Transporting Sediment from Location – Photo #03941

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SENE

Location ID: 334884

Date: 10/3/2024



Lack of Stabilization – Photo #03947