

Inspection Photos

API: 061-06296

Operator: STRACHAN EXPLORATION INC

Inspection Date: 10/3/2024



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing toward the wellsite.



Inspection Photos



Photo 2. Facing east toward the tank battery.



Inspection Photos



Photo 3. There is oily sludge on the berm that needs to be cleaned up.



Inspection Photos



Photo 4. The 2 strand fence is inadequate to prevent livestock entry. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06296 | Date: 10/3/2024