

Inspection Photos

API: 061-06353

Operator: STRACHAN EXPLORATION INC

Inspection Date: 10/3/2024



Inspection Photos



Photo 1. Center of the location facing north. Perennial vegetation has not established and there are undesirable weeds throughout the location.



Inspection Photos



Photo 2. Center of the location facing east. Perennial vegetation has not established and there are undesirable weeds throughout the location.



Inspection Photos



Photo 3. Center of the location facing south. Perennial vegetation has not established and there are undesirable weeds throughout the location.



Inspection Photos



Photo 4. Center of the location facing west. Perennial vegetation has not established and there are undesirable weeds throughout the location.



Inspection Photos



Photo 5. View of groundcover shows bare soils and undesirable weeds (Russian thistle).



Inspection Photos



Photo 6. Facing north toward the surrounding undisturbed pasture which consists of Native Bluer grama grassland.

