

Inspection Photos

API: 061-06394

Operator: STRACHAN EXPLORATION INC

Inspection Date: 10/3/2024



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the offsite tank battery location.



Inspection Photos



Photo 2. The fence around the tank has been repaired but there is an opening at this area and there are only 2 wires which will not keep livestock out.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06394 | Date: 10/3/2024

Inspection Photos



Photo 3. Facing northwest toward the wellsite. The fence around the pumpjack is in disrepair and wont prevent livestock entry. A new well sign has been installed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06394 | Date: 10/3/2024

Inspection Photos



Photo 4. Facing east toward the wellsite. The are parts laying on the ground that should be removed.

