

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BEAVER CREEK 11-7-793

Location ID: 432702



Photo # 3191 From entrance to location




Photo # 3192 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BEAVER CREEK 11-7-793

Location ID: 432702



Photo # 3193 Location



Photo # 3194 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BEAVER CREEK 11-7-793

Location ID: 432702



Photo # 3195 Location



Photo # 3196 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BEAVER CREEK 11-7-793

Location ID: 432702



Photo # 3197 Location

Photo # 3198 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BEAVER CREEK 11-7-793

Location ID: 432702



Photo # 3199 Location



Photo # 3200 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BEAVER CREEK 11-7-793

Location ID: 432702



Photo # 3201 Location



Photo # 3202 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BEAVER CREEK 11-7-793

Location ID: 432702



Photo # 3203 Location

Photo # 3204 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BEAVER CREEK 11-7-793

Location ID: 432702



Photo # 3205 Location



Photo # 3206 Burner exhaust open ended/available for entry by wildlife/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BEAVER CREEK 11-7-793

Location ID: 432702



Photo # 3207 Open ended load line



Photo # 3208 Same open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BEAVER CREEK 11-7-793

Location ID: 432702



Photo # 3209 Debris



Photo # 3210 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BEAVER CREEK 11-7-793

Location ID: 432702



Photo # 3211 Tank battery lacks signage/does not comply with CECMC rules



Photo # 3212 Tank label lacks capacity