

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/30/2024

Submitted Date:

09/30/2024

Document Number:

714201725

**FIELD INSPECTION FORM**Loc ID 332926 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 11 Number of Comments
- 3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Tibbs, Dan	970-539-0664	Dtibbs@kpk.com	
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	<a href="#">all inspections.</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241391	WELL	PR	05/01/2018	OW	123-09180	CLEVELAND 8	SI

**General Comment:**[This is an audit of CLEVELAND #8 scout card and related documents followed by a field inspection.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Storage of supplies. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	10/30/2024
Type	UNUSED EQUIPMENT		
Comment:	unused/disconnected equipment near the pumpjack. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	10/30/2024
Type	WEEDS		
Comment:	overgrown vegetation on various areas of location. See attached photos.		
Corrective Action:	Comply with rule 606.	Date:	10/30/2024

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241391

Type: WELL

API Number: 123-09180

Status: PR

Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/03/2024

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Optical Gas Imaging Survey**Survey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.114600 Long: -104.903300Wind: Gusts Speed: 16 (mph) Direction From: NE Weather: Clear Temperature: 75 (F)Assisting Staff Brittani Santistevan Camera #: \_\_\_\_\_☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
1302	PM	1305	PM	Wellhead(s)

Comment: The wellhead does not appear to be ommitting emissions into the atmosphere. See attached photos.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
<p><b>ECMC Inspection Report Summary</b> <b>WEATHER CONDITIONS:</b> sunny, dry ground. On Monday, September 30, 2024 at approximately 1300, I, Inspector Brittani Santistevan, conducted an on-site inspection at CLEVELAND #8 (KP Kauffman Company, Inc.), at location ID: 332926 in WELD COUNTY, Colorado. While there, I observed a shut-in facility. During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"><li>1. It appears to be overgrown vegetation on various areas of location. Remove to Comply with Rule 606. (Corrective Action Date: October 30, 2024) See attached photo #1, 4, 6.</li><li>2. It appears to be disconnected/unused equipment to pumpjack on location. Reconnect or remove from location to comply with Rule 606. (Corrective Action Date: October 30, 2024) See attached photo #5.</li><li>3. It appears to be some supplies being stored on location. Remove to comply with Rule 606. (Corrective Action Date: October 30, 2024) See attached photo #3.</li></ol> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	09/30/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403940575	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6728250">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6728250</a>
714201726	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6728240">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6728240</a>
714201736	Wellhead Video	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6728241">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6728241</a>