

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/30/2024

Submitted Date:

09/30/2024

Document Number:

714201727

FIELD INSPECTION FORMLoc ID 332884 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		cogcc@kpk.com	All Inspections
Tibbs, Dan	970-539-0664	Dtibbs@kpk.com	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240492	WELL	SI	06/01/2024	OW	123-08280	CLEVELAND 2	TA

General Comment:

This is an audit of CLEVELAND #2 scout card and related documents followed by a field inspection.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	unused/disconnected equipment. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	05/02/2024
Type	WEEDS		
Comment:	overgrown vegetation on various areas of location. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	10/30/2024

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 240492

Type: WELL

API Number: 123-08280

Status: SI

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; equipment appears to be disconnected.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/03/2024

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.111000 Long: -104.902800Wind: Gusts Speed: 17 (mph) Direction From: NE Weather: Clear Temperature: 75 (F)Assisting Staff Brittani Santistevan Camera #: _____☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
1327	PM	1329	PM	Wellhead(s)

Comment: The wellhead appears to not be ommitting emissions into the atmosphere. See attached video.

Corrective Action: _____ Date: _____

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>WEATHER CONDITIONS: sunny, dry ground.</p> <p>On Monday, September 30, 2024 at approximately 1315, I, Inspector Brittani Santistevan, conducted an on-site inspection at CLEVELAND #2 (KP Kauffman Company, Inc.), at location ID: 332884 in WELD COUNTY, Colorado.</p> <p>While there, I observed a TA wellhead.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. It appears to be overgrown vegetation on various areas of location. Remove to Comply with Rule 606. (Corrective Action Date: October 30, 2024) See attached photo #1, 3-5.</p> <p>2. It appears to be disconnected/unused equipment to pumpjack on location. Reconnect or remove from location to comply with Rule 606. (Corrective Action Date: May 2, 2024) See attached photo #5.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	09/30/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403940576	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6728251
714201728	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6728242
714201735	Wellhead Video	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6728243