

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 31-17 Pad

Location ID: 452011



Photo # 3585 From entrance to location



Photo # 3586 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 31-17 Pad

Location ID: 452011



Photo # 3587 Location



Photo # 3588 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 31-17 Pad

Location ID: 452011



Photo # 3589 Location




Photo # 3590 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 31-17 Pad

Location ID: 452011



Photo # 3591 Location



Photo # 3592 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 31-17 Pad

Location ID: 452011



Oct 2, 2024 at 3:22:53 PM
CO



Oct 2, 2024 at 3:23:23 PM
CO

Photo # 3593 Location

Photo # 3594 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 31-17 Pad

Location ID: 452011



Photo # 3595 Location



Photo # 3596 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 31-17 Pad

Location ID: 452011



Photo # 3597 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules



Photo # 3598 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 31-17 Pad

Location ID: 452011



Photo # 3599 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 3600 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 31-17 Pad

Location ID: 452011



Photo # 3601 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 3602 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RU 31-17 Pad

Location ID: 452011



Photo # 3603 Debris