

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/07/2024

Submitted Date:

10/07/2024

Document Number:

715500774**FIELD INSPECTION FORM**Loc ID 315367 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**ECMC Operator Number: 74290Name of Operator: RETAMCO OPERATING INCAddress: PO BOX 790City: RED LODGE State: MT Zip: 59068**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gose, Tom	(210) 216-0819	tomgose@retamco.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Engineering, ECMC		dnr_cogccengineering@state.co.us	
Johnson, Joe	(406) 446-1568	joejohnson@retamco.com	
Glennon, Joe	(406) 446-1568	joeglennon@retamco.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
103752	PIT	AC	09/23/1999		-	PHILADELPHIA CREEK 35	AC
230711	WELL	SI	04/01/2022	GW	103-08379	PHILADELPHIA CREEK 35	SI

**General Comment:****ECMC Inspection Report Summary**

On Monday, 10/07/2024, Inspector Kirby Burchett, conducted a routine field inspection at Retamco Operating Inc on the Philadelphia Creek 35 well, Location #315367, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District and Black Bear area with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations no compliance issues were observed.

Review of production records indicate well is overdue for a Mechanical Integrity Test

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Glycol label on separator		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Produced water label coming loose. Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 406-446-1568

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Tank open to wildlife. All stacks, vents, or other openings will be equipped with screens or other appropriate equipment to prevent entry by wildlife, including birds and bats.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PIT		
Comment:	Livestock wire		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date	
Type: Other	# 1				
Comment: Wellhead tree					
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:				Date:	
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 1				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	STEEL AST		,
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment: 22 ft x 24 ft unlined berm could be deemed inadequate to contain 150% tank capacity if any standing fluid is present inside tank berm				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	103752	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	AC
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	230711	Type:	WELL	API Number:	103-08379	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: Shut In - April 2022 July 2024 Production Report Well is overdue for Mechanical Integrity Test (MIT). MIT requires 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well.									
Corrective Action: Perform successful mechanical integrity test. If a successful MIT cannot be performed within 30 day CA time the well must be plugged within 3 months.									
Date: 11/07/2024									
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NOPit ID: 103752Lat: 39.910149Long: -108.706279

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_

Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

Date: \_\_\_\_\_

**Fencing:**Fencing Type: Wildlife

Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

Date: \_\_\_\_\_

**Netting:**Netting Type: Mesh

Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_

Oil Accumulation: \_\_\_\_\_

2+ feet Freeboard: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

Date: \_\_\_\_\_

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715500775	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6736713">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6736713</a>