

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2024

Submitted Date:

10/01/2024

Document Number:

708904707**FIELD INSPECTION FORM**

Loc ID 323788	Inspector Name: Smelser, Wayne	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b>  <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b>  13 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested  <b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>
<b>Operator Information:</b>  ECMC Operator Number: <u>10550</u>  Name of Operator: <u>MUSTANG RESOURCES LLC</u>  Address: <u>P O BOX 13550</u>  City: <u>BAKERSFIELD</u> State: <u>CA</u> Zip: <u>93389</u>				

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
, Mustang		nwelch@vaqueroenergy.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210809	WELL	SI	04/01/2024	GW	045-06567	MOORE 27-42-6S-94W	SI

<b>General Comment:</b>  CECMC Inspection Report Summary On 09/26/2024 at approximately 11:14 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad. Location # 323788 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Nest/Roost sites & in close proximity to NSO Habitat area. Location is approximately 104 yards from the Colorado River & 321 yards from Porcupine Creek. While there, I observed normal production operations.  During this inspection the following compliance issues were observed:  1. Housekeeping - Weeds near wellhead & meter house that are causing a fire hazard with a CA date of 10/08/2024  A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection report.
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	BATTERY			
Comment:	No tank battery			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/888-291-8588			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	WEEDS			
Comment:	Weeds near wellhead & meter house that are causing a fire hazard			
Corrective Action:	Comply with CECMC weeds/undesirable plant species rules & safety rules			Date: 10/08/2024
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
Type: Gas Meter Run	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:	Well is not on plunger lift			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.			
Corrective Action:				Date:
Type: Deadman # & Marked	# 1			
Comment:	Marked			
Corrective Action:				Date:



Inspected Facilities									
Facility ID:	210809	Type:	WELL	API Number:	045-06567	Status:	SI	Insp. Status:	SI
Producing Well									
Comment:	Producing, well not on plunger lift								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Gravel				Sparse in some areas
Compaction						
Gravel						Sparse to none
Other						Small amount of rill erosion on location

Comment: Small amount of rill erosion on location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Housekeeping for corrective action	smelserw	10/01/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403942513	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6729759">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6729759</a>
708904709	Inspection 708904707 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6729754">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6729754</a>
708904710	Inspection 708904707 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6729755">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6729755</a>