

Inspection Photos

API: 061-06838

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 10/3/2024

County: KIOWA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the location. The soils around the conex have eroded and no BMP's have been installed. The H2S wind sock is missing. Previous CA's were not completed.



Inspection Photos



Photo 2. Facing toward the tank battery. The H₂S wind sock is missing. There is oily stained soils that extend the entire area of the containment from a previous spill that was never cleaned up. Previous CA's were not completed.



Inspection Photos



Photo 3. There are stained soils at the back side of the tank battery that must be cleaned up. Previous CA was not completed.



Inspection Photos



Photo 4. There is oily material inside the black containment which has no wildlife protections. There are stained soils around the tank battery that must be cleaned up. Previous CA was not completed.



Inspection Photos



October 3, 2024

+38.467199,-102.681479

Photo 5. Facing northwest at the backside of the tank battery. There is oily stained soils that extend the entire area of the containment from a previous spill that was never cleaned up. Previous CA was not completed.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06838 | Date: 10/3/2024

Inspection Photos



Photo 6. Facing north at the east side of the location. The soil near the conex have eroded and are bare of vegetation. This area must be stabilized to prevent further erosion.



Inspection Photos



Photo 7. There is a pile of oily contaminated soil material stored on location that must be removed and properly disposed. Previous CA was not completed.



Inspection Photos



Photo 8. Facing toward the wellsite. The chemical container has tipped over. Previous CA was not completed.



Inspection Photos



Photo 9. The chemical container at the backside has also tipped over. There are unused parts of the pumpjack laying on the ground that need to be removed.

