

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2024

Submitted Date:

10/08/2024

Document Number:

699700403

**FIELD INSPECTION FORM**

Loc ID 316411 Inspector Name: Heil, John On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10384  
 Name of Operator: GENESIS GAS & OIL COLORADO LLC  
 Address: 1141 NORTH LOOP 1604 E 105-414  
 City: SAN ANTONIO State: TX Zip: 78232

**Findings:**

- 7 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Cholas, Nick		nick.cholas@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Roberts, James		j75rober@blm.gov	BLM meeker

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273077	WELL	PR	11/01/2022	CBM	103-10462	CRU 14-15C-IN100	EI

**General Comment:**

ECMC Environmental Inspection. All previous unresolved CAs for this location still apply to this inspection.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unnecessary equipment throughout the location.		
Corrective Action:	Comply with Rule 606.	Date:	
Type	DEBRIS		
Comment:	Trash and debris throughout the location.		
Corrective Action:	Comply with Rule 606.	Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
	Tank		
Comment:	Potentially impacted material within the tank battery secondary containment structure.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.	Date:	
	WELLHEAD		
Comment:	Potentially impacted material adjacent to the wellhead.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.	Date:	
	Separator		
Comment:	Potentially impacted material adjacent to the wellhead.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.	Date:	

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 273077 Type: WELL API Number: 103-10462 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700404	20240924 Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6738176">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6738176</a>