

Inspection Photos
Location: Sheryl Lynn 22-31
Location ID: 308912
API # 05-071-08798



Photo 1 –Well placard on meter house



Photo 2 – KV wellhead and equipment

Inspection Photos
Location: Sheryl Lynn 22-31
Location ID: 308912
API # 05-071-08798



Photo 3 – Meter house



Photo 4 – Wood pallets on location

Inspection Photos
Location: Sheryl Lynn 22-31
Location ID: 308912
API # 05-071-08798



Photo 5 – Wood pallets on location



Photo 6 – Pit Facility ID 301072

Inspection Photos
Location: Sheryl Lynn 22-31
Location ID: 308912
API # 05-071-08798



Photo 7 – Pit Facility ID 301072, Stormwater entering pit



Photo 8 – Erosion along access road