

Inspection Photos
Location: Fanny 34-29
Location ID: 308866
API # 05-071-08744



Photo 1 –Well placard on meter house



Photo 2 – KV wellhead and equipment

Inspection Photos
Location: Fanny 34-29
Location ID: 308866
API # 05-071-08744



Photo 3 – Meter house



Photo 4 – Pit Facility ID 285706

Inspection Photos
Location: Fanny 34-29
Location ID: 308866
API # 05-071-08744



Photo 5 – Engine skid



Photo 6 – Undesirable weeds

Inspection Photos
Location: Fanny 34-29
Location ID: 308866
API # 05-071-08744



Photo 7 – Erosion along access road



Photo 8 – Erosion along access road