

# Inspection Photos

Loc: 324797

Operator: WESTERN OPERATING COMPANY

Inspection Date: 10/3/2024

County: KIOWA



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing north along the flowline disturbance. The soils along the flowline need to be regraded and reclaimed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 324797 | Date: 10/3/2024

## Inspection Photos



**Photo 2.** Facing east along the main access road. The road is below the grade of the land and causes issues with snow accumulation during the winter.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 324797 | Date: 10/3/2024

## Inspection Photos



**Photo 3.** Facing east at the tank battery. Tanks have been installed with secondary containment.



Inspection Photos



**Photo 4.** Facing southwest at the tank battery location. The flowline disturbance must be reclaimed and stabilized..



## Inspection Photos



**Photo 5.** Facing toward the stockpile of soil which remains bare and susceptible to erosion.



## Inspection Photos



**Photo 6.** Facing east at the south side of the tank battery. It appears the stock piled soils have wind blown and almost completely covered up the perimeter wattles shown at red arrow.



Inspection Photos



**Photo 7.** South side of the tank battery location facing north.



Inspection Photos



**Photo 8.** Facing northwest toward the remediation disturbance.



Inspection Photos



**Photo 9.** Facing northwest toward the remediation disturbance.



Inspection Photos



**Photo 10.** Facing east at the wellsite.

