

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/03/2024

Submitted Date:

10/08/2024

Document Number:

713601500

FIELD INSPECTION FORM

Loc ID 324789 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 95620
Name of Operator: WESTERN OPERATING COMPANY
Address: 1165 DELAWARE STREET #200
City: DENVER State: CO Zip: 80204

Findings:

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hart, Dale	719-688-1638	dale@westernoperating.com	
James, Steven	(303) 893-2438	steve@westernoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324789	LOCATION	AC			-	WEAR-619S45W 5NWSE	RI

General Comment:

This is a follow up of the previous inspections (#713600591, #713600791, #713601027).
The corrective action of the previous inspections have not been completed.
See attached photos and additional details within this report.
Operator is directed to perform corrective actions outlined on this inspection report immediately.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	There did not appear to be labeling placards on the tanks.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	11/08/2024

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	There are various supplies and debris stored inside the dilapidated storage shed which appears to be an extreme fire hazard adjacent to the tank battery. There are chemical containers, parts, debris, trash, and various other materials laying on the ground. The stored supplies does not appear to have been used for a long duration of time and is not in use. All unused supplies, containers, materials, and equipment must be removed. Previous corrective action was not completed		
Corrective Action:	Comply with Rule 606 for Good Housekeeping and Rule 610 Fire Prevention and Protection.	Date:	01/10/2024
Type	OTHER		
Comment:	The storage shed adjacent to the tank battery is in disrepair. There are loose rattling metal pieces that may fall off. The shed must be repaired or removed if no longer in use. It appears part of the roof was repaired however the back west side still remains in disrepair. Previous corrective action was not completed.		
Corrective Action:	Comply with Rule 606 and Rule 608.e.	Date:	01/10/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	A new perimeter barbed wire fence was installed at the location.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601501	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6738453