

# Interim Reclamation and Stormwater Inspection

Date: 09/30/2024

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 312228

Inspection Document #: 708201669

Logan County, CO




**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Propst #C-1X  
Location ID: 312228



**Photo 1.** Wildlife netting has been installed around secondary containment. NFPA Placard does not appear to have been installed since the previous inspection.

Inspection Photos  
Location Name: Propst #C-1X  
Location ID: 312228



**Photo 2.** Erosion degradation evident on the western portion of the production areas. No apparent stormwater control measures/BMPs observed at the time of this inspection.

Inspection Photos  
Location Name: Propst #C-1X  
Location ID: 312228



**Photo 3.** Erosion degradation evident on the southwestern portion of the production areas. No apparent stormwater control measures/BMPs observed at the time of this inspection.

Inspection Photos  
Location Name: Propst #C-1X  
Location ID: 312228



Photo 4. Continued from Photo 3.

Inspection Photos  
Location Name: Propst #C-1X  
Location ID: 312228



**Photo 5.** Pipe (debris) remains from the previous inspection; south of the well location in nearby drainage.

Inspection Photos  
Location Name: Propst #C-1X  
Location ID: 312228



**Photo 6.** South of the well, interim areas appear to be progressing towards Rule 1003 vegetative standards.

Inspection Photos  
Location Name: Propst #C-1X  
Location ID: 312228



**Photo 7.** Erosion degradation evident on the southeastern portion of the production areas. No apparent stormwater control measures/BMPs observed at the time of this inspection.

Inspection Photos  
Location Name: Propst #C-1X  
Location ID: 312228



**Photo 8.** Continued from Photo 7.

Inspection Photos  
Location Name: Propst #C-1X  
Location ID: 312228



**Photo 9.** Northeastern guyline anchor maker needs to be reinstalled.